

03560.003025

PATENT

*Cofle*

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE



On re Patent of: )  
SUSUMU YASUDA, et al. )  
Appl. No.: 10/073,304 )  
Filed: February 13, 2002 )  
For: TILTABLE-BODY APPARATUS, )  
AND METHOD OF FABRICATING )  
THE SAME )  
U.S. Patent No.: 6,831,765 )  
Issued: December 14, 2004 )  
 ) November 30, 2005  
Examiner: James Phan  
Group Art Unit: 2872

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

**Certificate**  
**DEC 06 2005**  
**of Correction**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/02/2005 HDEMESS1 00000027 6831765

01 FC:1811

100.00 0P

DEC 6 2005

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Edward A. Kmett  
Attorney for Patentees  
Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

CA\_MAIN 104846v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,831,765

DATED : December 14, 2004

INVENTOR(S) : SUSUMU YASUDA, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 53, "occurs" should read --occur--.

COLUMN 7:

Line 1, "across-sectional" should read --a cross-sectional--.

Line 25, "across-sectional" should read --a cross-sectional--.

Line 51, "across-sectional" should read --a cross-sectional--.

COLUMN 9:

Line 45, "Si0<sub>2</sub>" should read --SiO<sub>2</sub>--.

Line 55, "W," should read --W<sub>a</sub>--.

COLUMN 10:

Line 67, "is" should read --are--.

COLUMN 11:

Line 50, "up-side-down" should read --upside down--.

COLUMN 13:

Line 40, "occurs" should read --occur--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,831,765

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)  
(Form#30)

DEC 6 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,831,765

DATED : December 14, 2004

INVENTOR(S) : SUSUMU YASUDA, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 66, "629;" should read --629,--.

COLUMN 17:

Line 50, "up-side-down" should read --upside down--.

Line 59, "there is" should read --there are--.

COLUMN 18:

Line 59, "a acceleration" should read --an acceleration--.

COLUMN 20:

Line 38, "occurs" should read --occur--.

COLUMN 21:

Line 34, "p:" should be deleted.

COLUMN 25:

Line 4, "occurs" should read --occur--.

COLUMN 30:

Line 25, "said" should read --said each--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,831,765

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30)

→ \_\_\_\_\_

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,831,765

DATED : December 14, 2004

INVENTOR(S) : SUSUMU YASUDA, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 53, "occurs" should read --occur--.

COLUMN 7:

Line 1, "across-sectional" should read --a cross-sectional--.

Line 25, "across-sectional" should read --a cross-sectional--.

Line 51, "across-sectional" should read --a cross-sectional--.

COLUMN 9:

Line 45, "Si0<sub>2</sub>" should read --SiO<sub>2</sub>--.

Line 55, "W," should read --W<sub>a</sub>--.

COLUMN 10:

Line 67, "is" should read --are--.

COLUMN 11:

Line 50, "up-side-down" should read --upside down--.

COLUMN 13:

Line 40, "occurs" should read --occur--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,831,765

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)  
(Form#30)

→ \_\_\_\_\_  
DEC 6 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,831,765

DATED : December 14, 2004

INVENTOR(S) : SUSUMU YASUDA, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 66, "629;" should read --629,--.

COLUMN 17:

Line 50, "up-side-down" should read --upside down--.

Line 59, "there is" should read --there are--.

COLUMN 18:

Line 59, "a acceleration" should read --an acceleration--.

COLUMN 20:

Line 38, "occurs" should read --occur--.

COLUMN 21:

Line 34, "p:" should be deleted.

COLUMN 25:

Line 4, "occurs" should read --occur--.

COLUMN 30:

Line 25, "said" should read --said each--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,831,765No. of add'l. copies  
@ 30¢ per pageForm PTO 1050 (Rev. 3-82)  
(Form#30)→ \_\_\_\_\_  
DEC 6 2005